



Radon Mitigation Quality Assurance Test

The goal of this test is to assure functionality of installed radon mitigation systems in the building. Two alternate occupied rooms from the list below will be tested yearly.

Building Information	3002	District	ASD-W
Building Name:	Central New Brunswick Academy		
Year constructed	2010	Phase	5
Street Address:	7263 Route 8 Hwy		
City:	New Bandon		

Ventilation System	Y \ N	Mitigation System	Y \ N
			Telephone Number

Facilities Manager:	Philip Cliff	
Name of Person Placing Detectors:	Peter Luce	476-0216

Instructions:

Installation

- 1) Choose two rooms below, if "R" is indicated in front of the room number, this room must be tested.
- 2) Write the detector number on the corresponding room number line
- 3) Write the installation date on the corresponding room number line.
- 4) Write the installation date on the detector (Start Date).
- 5) Fax a copy of this sheet after the installation has been complete to (506) 444-5529 or email to pascal.landry@gnb.ca.
- 6) Keep this page for the duration of the test and return with detectors.

Collection The duration of the test will be 90 days.

- 1) Collect the two detectors after 90 days
- 2) Write the collection date on the detector.
- 3) Write the collection date on the corresponding line below.
- 4) Return the two detectors and this form to:

**Att: Pascal Landry
Educational Facilities
250 King Street, Place 2000
Fredericton, NB
E3B 9M9**

Central New Brunswick Academy

Room No.	Serial Number	Installation Date day/month/year	Collection Date day/month/year	Result Bq/m ³	Uncertainty
R 137	323463	29/03/2016	24/06/2016	263 ± 3%	
R 136	323459	29/03/2016	24/06/2016	270 ± 3%	
R 139	323467	29/03/2016	24/06/2016	285 ± 3%	
R 140	323468	29/03/2016	24/06/2016	318 ± 3%	
R 142	323460	29/03/2016	24/06/2016	255 ± 3%	
R 133	323472	29/03/2016	24/06/2016	266 ± 3%	
R 132	323471	29/03/2016	24/06/2016	133 ± 5%	
R 118	323461	29/03/2016	24/06/2016	244 ± 4%	
R 119	323466	29/03/2016	24/06/2016	107 ± 5%	
R 116	323464	29/03/2016	24/06/2016	85 ± 6%	
R 182	323469	29/03/2016	24/06/2016	67 ± 6%	
R 193	323470	29/03/2016	24/06/2016	48 ± 7%	
R 123	323462	29/03/2016	24/06/2016	56 ± 7%	
R 114	323465	29/03/2016	24/06/2016	56 ± 7%	

Fax form to (506) 444-5529 after installation of detectors.
Return completed document after collection of detectors