

Building Interior and Additions	Item	Description	Rationale	Priority
Interior accessibility	Lift	Wheel chair lift and automatic door openers	Project added to meet coding requirements and potential future student needs	2
Interior	Flooring	Floor replacements	Project added to replace the life expectancy of existing flooring	3
Interior alterations and renovations	Office	Office relocation	For security purposes, to be closer to the main entrance of the school	3
Building Envelope	Roof Replacement	Peaked roof with shingle	Project added to replace the life expectancy of existing roof shingles	2
Building Envelope	Exterior	Siding replacement	Project added to replace the life expectancy of existing siding	3
Site	Site Improvement	Paving	Current gravel driveway, bring to the educational standard specifications	3
Building Envelope	Windows	North side window replacement	added to replace at life expectancy of existing windows	2
Electrical	Communications	Intercom system throughout school	Current system offers only one way communication, we would consider this a low priority number 1	1
Water supply and sewer	Water supply and distribution	Backflow prevention	Project added to meet educational standard specifications	2
Electrical	Electrical Supply and Distribution	Electrical upgrade (panels)	Project added to replace the life expectancy of existing electrical components	2
Heating and Ventilation	Ventilation System	Ventilation system and electrical upgrade	Project added to meet educational standard specifications, currently there is no system in the school	2