



Radon Mitigation Quality Assurance Test

The goal of this test is to assure functionality of installed radon mitigation systems in the building. Two alternate occupied rooms from the list below will be tested yearly.

| | | | |
|--|------------------------------|--------------------------|-------|
| Building Information | 2413 | District | ASD-W |
| Building Name: | Chipman Forest Avenue School | | |
| Year constructed | 1988 | Phase | 4 |
| Street Address: | 33 Forest Avenue | | |
| City: | Chipman | | |
| Ventilation System | Y \ N | Mitigation System | Y \ N |
| Telephone Number | | | |
| Facilities Manager: | | | |
| Name of Person Placing Detectors: | | | |

Instructions:

Installation

- Choose two rooms below, if "R" is indicated in front of the room number, this room must be tested.
- Write the detector number on the corresponding room number line
- Write the installation date on the corresponding room number line.
- Write the installation date on the detector (Start Date).
- Fax a copy of this sheet after the installation has been complete to (506) 444-5529 or email to pascal.landry@gnb.ca.
- Keep this page for the duration of the test and return with detectors.

Collection The duration of the test will be 90 days.

- Collect the two detectors after 90 days
- Write the collection date on the detector.
- Write the collection date on the corresponding line below.
- Return the two detectors and this form to:

**Att: Pascal Landry
Educational Facilities
250 King Street, Place 2000
Fredericton, NB
E3B 9M9**

Chipman Forest Avenue School

| Room No. | Serial Number | Installation Date day/month/year | Collection Date day/month/year | Result Bq/m ³ | Uncertainty |
|------------|---------------|-------------------------------------|-----------------------------------|-----------------------------|-------------|
| Music Room | | | | | |
| Office | 269688 | 13/11/2013 | 15/05/2014 | 189 | |
| 111 | 323409 | 04/02/2016 | 09/05/2016 | 185 ± 4% | |
| Library | 269687 | 13/11/2013 | 15/05/2014 | 174 | |
| 110 | 323410 | 04/02/2016 | 09/05/2016 | 207 ± 4% | |
| | | | | | |

Fax form to (506) 444-5529 after installation of detectors.
Return completed document after collection of detectors