

## Radon Mitigation Quality Assurance Test

	test is to assure functional ied rooms from the list belo	ity of installed radon mitigat ow will be tested yearly.	ion systems in the b	uilding. Two		
Building Information		0901	District	ASD-W		
Building Nam		Doaktown Elementary		7.02 11		
Year constructed Street Address: City:		1988 <b>Phase</b> 6				
		430 Main Street Doaktown				
Ventilation System Y \ N		Mitigation System Y \ N		1		
			Tel	lephon Number		
Facilities Manager: Name of Person Placing Detectors:			I	•		
					1	
Instructions:			•		1	
Installation					1	
3) Write the ins 4) Write the ins 5) Fax a copy of pascal.landry@ 6) Keep this pa Collection 1) Collect the to 2) Write the col 3) Write the col 4) Return the to	stallation date on the corres stallation date on the detect of this sheet after the install gnb.ca.	est and return with detectors  The duration of	(506) 444-5529 or e s. of the test will be Att: Pascal I Educational	90 days. Landry Facilities eet, Place 2000		
Doaktown Ele	ementary School				ł	
Room No.	Serial Number	Installation Date day/month/year		ction Date onth/year	Result Bq/m³	Uncertainty
102						
103	323411	29/01/2016	19/0	05/2016	26	6 ± 9%
104						
202A						
203	323412	29/01/2016	19/0	05/2016	22	2 ± 9%
205						
303						
305						
Gym Office						